Facility Detail for:

Peninsula Plating

Route 5 Box 1C, Blades, DE 19973 US Street Address: Type: Other Industrial Plant



	: N		

Primary Names Aliases

Site investigation & Restoration Site (S/RS)

Peninsula Plating

Program Detail for:

Peninsula Plating

Program: Site Investigation & Restoration Site (SIRS) Program Assigned ID: DE-0287



Location	nfor	matic	on				*************		000000000000000000000000000000000000000	***************		000000000000	***************************************		000000000000000000000000000000000000000		******************	1000000000000000		000000000000000000000000000000000000000			************	00000000	000000000000000000000000000000000000000
Location Peninsula Plating																									
Site Name: Peninsula Plating						Ref	Reference Pt:			Unknown				Horizontal Method				d: Unknown							
		testoration Site				ude (dec): 38.63				2222 Longitu			de: [-75.610550 X			X (N	AD 83m): 1			33095.95 Y		': L	70256.1	
County:	Si	Gussex State: Delaware						re	Town: Blades			des	PO			PO N	O Name: Seaford					ZIP	5: [19973	
Sewer Di	: Blades				FloodPlain Zone:							SRA:		-				Basin: Chesap		esape	peake Bay				
Watershed: Nanticoke Riv			Rive	r	DRBC Basin: N					Quad:			SEAFORD EA			EAST	T School Distric			:					
Senate D	t: 21 Senator:			itor:	District 21 - Sen Brya Richardson			nt L.	nt L. House I			istrict: 39		Re	lepresentative:			District 39 - Rep Daniel B Short							
GMZ Nan	ne:				7	Ag F	res l	District:					Wate	er Di	istrict	: [Mod	Grid:	T			

Owner Information

No Owner Information Available Regulatory Status

No Regulatory Status Information Available Permit Information

No Permit Information Available Tank Information

No Under-Ground Tank Information Available No Above-Ground Tank Information Available Inspection Information

Facility Detail Report

Inspection -- 11/30/1999

Start Date: 2/8/1999 Type: Site Inspection Announced: Multimedia: Site Investigation Program:

& Restoration Site

(SIRS)

Reason For: Core Program Investigation Completed Outcome: Results:

Lead Person: Lead Agency: Consultant:

Inspection -- 2/20/2007

12/5/2006 **Type: Start Date:** Remedial Investigation Announced: Multimedia: Site Investigation Program: & Restoration Site

(SIRS)

Reason For: Core Program Investigation Completed Outcome: Results:

Lead Person: Lead Agency: Consultant:

Inspection -- 4/28/2007

Start Date: 4/28/2007 Type: Feasiblity Study Announced: Multimedia: Program: Site Investigation

& Restoration Site (SIRS)

Reason For: Core Program Outcome: Investigation Completed Results: NFA

Lead Person: Lead Agency: Consultant:

Inspection -- 4/30/2007

Start Date: 4/30/2007 Type: Proposed Plan Announced: Multimedia: Program: Site Investigation

& Restoration Site

(SIRS)

Reason For: Core Program Outcome: Results:

Lead Person: Lead Agency: Consultant:

Violation Information

No Violation Information Available Enforcement Action Information

No Enforcement Action Information Available LUST Projects Information

No LUST Project Information Available SIRB Information

Prog Assigned ID Site Name Site Type DE-0287 Peninsula Plating Other Industrial Plant

Outfalls Information

No Outfalls Information Available